

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

March 24, 2010

TO:	Internal File		
THRU:	Daron Haddock, Permit Supervisor		
FROM:	James D. Smith, Environmental Scientist $\int \mathcal{S} 24 10 $		
RE:	2009 Third Quarter Water Monitoring, PacifiCorp, Cottonwood/Wilberg Mine, C/015/00 Task ID #3376	<u>19,</u>	
The Co	Cottonwood/Wilberg Mine monitoring plan is described in Appendix A of Volume 9 of the M	1RP.	
monitoring sites only well monit	are no springs monitored at this site. The mine was sealed May 10, 2001, so in-mine es TMA @ 32 and 2 nd S XC-11 are no longer accessible. WCWR1 at the Waste Rock Site is itored. The pond at the Cottonwood Fan Portal was reclaimed in 2002 so UPDES 22896-00 reted to DOGM or the Division of Water Quality.	the 2 is	
1. We	ere data submitted for all of the MRP required sites?		
Stream	ms YES ⊠ NO □		
GWR02, and G operational para	ally and August, only flow is to be reported for CCC1 in Cottonwood Canyon and GWR01, GWR03 in Grimes Wash. In September, field parameters are to be reported for CCC1 and rameters for the three sites in Grimes Wash. For the 3 rd Quarter 2009, all required parameter at CCC1 and no-flow was reported for Grimes Wash.	rs	
Wells	YES ⊠ NO □		
	R1 at the Waste Rock Site is the only well monitored: it is monitored once a quarter for rameters plus B and Se.		
UPDE	YES ⊠ NO □		
operational para	s are submitted in electronic format (Adobe): DMR data are submitted to the DOGM database rameters, not as DMR parameters. During the 3 rd Quarter 2009, there was discharge all three fall 22896-001, and no discharge at outfalls 22896-004, 22896-004, and 22896-004.	se as e	
2. W	Vere all required parameters reported for each site?		

Streams	YES 🖂	NO 🗌		
Wells	YES 🖂	NO 🗌		
UPDES	YES 🛚	NO 🗌		
3. Were any irregularities found in the data?				
Listed parameters were outside two standard de	eviations.			
Streams	YES 🗌	NO 🛛		
Wells WCWR1 <u>September</u> : Mg.	YES 🖂	NO 🗌		
UPDES	YES 🗌	NO 🖾		
 4. On what date does the MRP require a five-year resampling of baseline water data. The Division received the permit renewal submittal on 03/09//09, for renewal on 07/06/09. Baseline analyses were performed in 2001 and 2006 and the next five-year baseline analyses will be in 2011. 5. Based on your review, what further actions, if any, do you recommend? 				
No further action is required at this time.				
6. Does the Mine Operator need to submit more in requirements?	formation to fulfill this qu	uarter's monitoring		
7. Follow-up from last quarter, if necessary. None.				
8. Did the Mine Operator submit all missing and/o	r irregular data?			
NA				